



Chart 2 Rehabilitation Assistance Up to \$5,000



Provide notice of lead hazard evaluation to residents within 15 days

Finalize the work write-up and bid the work to qualified contractors.

- For surfaces with lead-based paint, workers should be trained in lead-safe work practices or be supervised by a certified abatement supervisor.
- For surfaces with no lead-based paint, no special training or supervision is required.


Complete work
Use Lead Safe Work Practices and repair painted surfaces that will be disturbed during work.

Perform a clearance exam. (Must be performed by a licensed lead paint inspector, risk assessor, or lead sampling technician)



Notice of lead hazard reduction work performed provided to resident within 15 days.

Complete




Provide notice of presumption to residents within 15 days

Bid the work to qualified contractors. Because all painted surfaces are presumed to have lead-based paint, workers should be trained in lead-safe work practices or be supervised by a certified abatement supervisor.

Complete work
Use Lead Safe Work Practices and repair painted surfaces that will be disturbed during work.

Perform a clearance exam. (Must be performed by a licensed lead paint inspector, risk assessor, or lead sampling technician)



Reclean

Notice of lead hazard reduction work performed provided to resident within 15 days.

Continue with Rehabilitation and Re-occupancy